ISO 9001
ISO 14001
ISO 45001

BV

BUREAU VERITAS Certification

BV CERTIFIED FIRE VEHICLE

Reliable Fire Rescue Solution with Bureau Veritas Certification

ISO 9001

ISO 14001

ISO 45001

Certified Quality · Safety · Compliance

BV Ref. No.: GTS 2026 230294-1
Issuance Date: 05/08/2026

Lashing Condition Report

1. BV Ref. No.	:	GTS 2026 230294-1	2. Order Received	:	August 4, 2026
3. Location	:	Shanghai City, China	4. Inspection date	:	August 5, 2026
5. Vessel/Voyage	:	CSCL MERCURY/100W	6. B/L No.	:	COSU6462274720

Description of the goods to be loaded :

TRUCK

Total: 1PKGS

Condition of loaded cargo

7. Cargoes are properly stowed according to document
   Yes ☒ No ☐
8. The weight of cargo are evenly laid
   Yes ☒ No ☐
9. Cargoes are firmly fixed by lashing materials
   Yes ☒ No ☐
10. Sufficient wooden skids, wooden blocks, at bottom protection
   Skid ☐ Block ☒ Others ☐

Condition of Lashing Materials

11. Lashing materials / security appliances used

Steel wire	☒	Turn buckle	☒	Wire- U-Clip	☒
W/Skids	☐	W/Block	☒	Shackle	☒
W/cradle	☐	PP bands	☐	Nylon bands	☒

12. Stated of lashing materials.
   New ☒ Used ☐ Reconditioned ☐

Condition of Container:

13. Type of Container :
   Flat Rack ☒ Open Top ☐
   20' ☐ 40' ☒
14. Container particular:
   Declared loading capacity: 50,000KGS
15. Certification body:
   AB ☒ BV ☐ Lloyd's ☐ other s ☐
16. Visual condition
   Rusty ☐ Dent ☐ Bulge ☐ Good ☒
17. Rings and hooks
   Rusty ☐ Dent ☐ Bulge ☐ Good ☒
18. Flooring
   Clean & Dry ☒ Good ☐ Damaged or dirty ☐

Container No.	DFOU5001164
Seal No.	N/A
Declared Weight	10500KGS

Remarks:

1) L 755 *W 272 *H 381 cm
   Over Width : 14 / 14 cm
   Over height: 186 cm

Inspection Result:	Satisfactory ☒ Failed ☐
Inspection Time:	09:00 am ~16:30 pm
Travel ling Expenses:	RMB
Inspector's Signature:	Simon Liu
Shipper's Signature:	

This reflects the findings at time and place of our attendance.
Photos will be attached as one part of this report.

We now certify that the above inspection has been carried out according to Bureau Veritas General conditions and above findings are valid at time and place of inspection. The issuance of this inspection certificate does not release the contractual parties from their own responsibilities and the fulfillment of their obligations.
This report automatically expires 3 months from its issuance date, except expiration of the products.
Revision 1.1, 10/2025

Container number : DFOU5001164

We now certify that the above inspection has been carried out according to Bureau Veritas General conditions and above findings are valid at time and place of inspection. The issuance of this inspection certificate does not release the contractual parties from their own responsibilities and the fulfillment of their obligations.
This report automatically expires 3 months from its issuance date, except expiration of the products.
Revision 1.1, 10/2025

POWERSTAR

We now certify that the above inspection has been carried out according to Bureau Veritas General conditions and above findings are valid at time and place of inspection. The issuance of this inspection certificate does not release the contractual parties from their own responsibilities and the fulfillment of their obligations.
This report automatically expires 3 months from its issuance date, except expiration of the products.
Revision 1.1, 10/2025

Lashing Condition Report

1. BV Ref. No.	:	GTS 2026 230294-1	2. Order Received	:	August 4, 2026
3. Location	:	Shanghai City, China	4. Inspection date	:	August 5, 2026
5. Vessel/Voyage	:	CSCL MERCURY/100W	6. B/L No.	:	COSU6462274720

Description of the goods to be loaded :

TRUCK

Total: 1PKGS

Condition of loaded cargo

7. Cargoes are properly stowed according to document
   Yes ☒ No ☐
8. The weight of cargo are evenly laid
   Yes ☒ No ☐
9. Cargoes are firmly fixed by lashing materials
   Yes ☒ No ☐
10. Sufficient wooden skids, wooden blocks. at bottom protection
    Skid ☐ Block ☒ Others ☐

Condition of Lashing Materials

11. Lashing materials / security appliances used

Steel wire	☒	Turn buckle	☒	Wire- U-Clip	☒
W/Skids	☐	W/Block	☒	Shackle	☒
W/cradle	☐	PP bands	☐	Nylon bands	☒

12. Stated of lashing materials.
    New ☒ Used ☐ Reconditioned ☐

Condition of Container:

13. Type of Container :
    Flat Rack ☒ Open Top ☐
    20' ☐ 40' ☒
14. Container particular:
    Declared loading capacity: 52,500KGS
15. Certification body:
    AB ☐ BV ☐ Lloyd's ☐ other s ☒
16. Visual condition
    Rusty ☐ Dent ☐ Bulge ☐ Good ☒
17. Rings and hooks
    Rusty ☐ Dent ☐ Bulge ☐ Good ☒
18. Flooring
    Clean & Dry ☒ Good ☐ Damaged or dirty ☐

Container No.	FBIU4013827
Seal No.	N/A
Declared Weight	10200KGS

Remarks:

2) L 805 *W 267.5 *H 379 cm
   Over Width : 8 / 15.5 cm
   Over height: 184 cm

Inspection Result:	Satisfactory ☒ Failed ☐
Inspection Time:	09:00 am ~16:30 pm
Travel ling Expenses:	RMB
Inspector's Signature:	Simon Liu
Shipper's Signature:	

This reflects the findings at time and place of our attendance.
Photos will be attached as one part of this report.

We now certify that the above inspection has been carried out according to Bureau Veritas General conditions and above findings are valid at time and place of inspection. The issuance of this inspection certificate does not release the contractual parties from their own responsibilities and the fulfillment of their obligations.
This report automatically expires 3 months from its issuance date, except expiration of the products.
Revision 1.1, 10/2025

Container number : FBIU4013827

We now certify that the above inspection has been carried out according to Bureau Veritas General conditions and above findings are valid at time and place of inspection. The issuance of this inspection certificate does not release the contractual parties from their own responsibilities and the fulfillment of their obligations.
This report automatically expires 3 months from its issuance date, except expiration of the products.
Revision 1.1, 10/2025

We now certify that the above inspection has been carried out according to Bureau Veritas General conditions and above findings are valid at time and place of inspection. The issuance of this inspection certificate does not release the contractual parties from their own responsibilities and the fulfillment of their obligations.
This report automatically expires 3 months from its issuance date, except expiration of the products.
Revision 1.1, 10/2025

ZJARRFIKËSE
BASHKIA VLORË
128

C128
C128

C128
MZSH
C128

车护航千万家
Chariots escort countless families.
BASHKIA VLORË
MZSH
128